

Indication	Wrench lamp	Spanner	Detection ECU	Error mode	Phenomenon on vehicle	Described on page
62-1	62-1	Blinking	SAS/OPS	Tilt angle sensor open abnormality	Partial limitation of mast control function	19-78
62-2	62-2	Blinking	SAS/OPS	Tilt angle sensor VCC short abnormality		
63-1	63-1	Blinking	SAS/OPS	Tilt switches simultaneously ON		
63-2	63-2	Blinking	SAS/OPS	Tilt switch forward tilt SW short	Partial limitation of mast control function	19-81
63-3	63-3	Blinking	SAS/OPS	Tilt switch backward tilt SW short		
64-1	64-1	Blinking	SAS/OPS	Lift lower lock solenoid open circuit or load short abnormality	Lift lower may stop	19-84
65-1	65-1	Blinking	SAS/OPS	Tilt control solenoid open circuit or load short abnormality	Forward tilt may stop, backward tilt may go fully back	19-86
66-1	66-1	Blinking	SAS/OPS	Outside matching value range for tilt angle error	Partial limitation of mast control function	19-88
67-1	67-1	Blinking	SAS/OPS	Lifting height switch open abnormality	Partial limitation of the rear wheel swing control function Partial limitation of mast control function Limitation of the drive control function Load indicator display is unsteady	19-89
68-1	68-1	Blinking	SAS/OPS	Lift switch raise and lower simultaneously ON error	Lowering may stop Function of automatic idle speed increase during lifting limited	19-92
68-2	68-2	Blinking	SAS/OPS	Lift switch raise SW short abnormality	Function of automatic idle speed increase during lifting limited	
68-3	68-3	Blinking	SAS/OPS	Lift switch lower SW short abnormality	Lowering may stop	
69-1	69-1	Blinking	SAS/OPS	Backward tilt lock solenoid open circuit or load short abnormality	Backward tilt may stop	19-95
71-1	71-1	Blinking	SAS/OPS	Tire angle sensor open abnormality	Knob offset compensation stops	19-97
71-2	71-2	Blinking	SAS/OPS	Tire angle sensor VCC short abnormality		
72-1	72-1	Blinking	SAS/OPS	Steering-wheel angle sensor SS1 open abnormality	Knob offset compensation stops	19-100
72-2	72-2	Blinking	SAS/OPS	Steering-wheel angle sensor SS2 open abnormality		
72-3	72-3	Blinking	SAS/OPS	Steering-wheel angle sensor SSC open abnormality		
72-4	72-4	Blinking	SAS/OPS	Steering-wheel angle sensors SS1 and SS2 open abnormality		